



## A-10 METAL PRIMER

**Quick Drying Industrial Primer**

### Description

Quick Drying Industrial Primer for interior and exterior surfaces. It is used as a primer for **A-10 Quick Drying Industrial Enamels** and **Pelespeed** (Peletico's products). It is suitable for new steelwork, machinery and all types of metal structures.

### Technical Specifications

Vehicle type	:	Styrene modified Alkyd Resin
Specific Gravity	:	1.19±0.04 (for Grey colour) 1.48±0.04 (for Red Oxide colour)
Weight solids	:	52±1%
Viscosity	:	75±5" Ford Cup No.4 (for Grey colour) 110±10" Ford Cup No.4 (for Red Oxide colour)
Coverage	:	11-13m <sup>2</sup> /L / coat
Dilution with airless spray	:	Up to 10%, by volume
Drying time at 25°C and relative humidity 50%	:	Touch dry: 5-10 minutes Through drying: 2-3 hours, depending on weather conditions
Flash point	:	<60°C
<b>European Union Limit for this product (Cat. A/i): 500g/l (2010). This product contains max 490g/l VOC</b>		

### Instructions for Use

#### SURFACE PREPARATION

Remove all surface contamination, e.g. dust, oil stains, dampness or other contaminants, using **Thinner 11/11** (Peletico's product). Peeling or cracked paint should be scraped off and sanded to a sound surface. It is recommended, prior to final decoration, on bare metal surfaces. Apply a first coat of **A-10 Metal Primer** and after 5-10 minutes a subsequent crosswise coat is applied.

#### APPLICATION

**Thinning/Cleaning:** **Thinner 11/11** (Peletico's product).

**Application tools:** Airless Spray.

**Application Temperature:** Ideal temperature for the application should be between 5-35°C and the relative humidity should not exceed 80%.

Stir well before use.

**Cleaning of Tools:** Remove as much paint as possible from tools and clean immediately with Thinner 11/11.

**PACKING:** 1L, 2.5L, 4L & 20L.

**COLOUR RANGE:** Grey and Red Oxide.

**STORAGE:** Store in a dry place, away from direct sunlight and/or extreme temperatures. Close the container after application.



## Health and Safety Measures

- Keep out of reach of children.
- Flammable liquid and vapour.
- Causes skin irritation.
- Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking.
- Keep container tightly closed.
- Wash with water and soap thoroughly after handling.
- Wear protective gloves / eye protection / face protection.
- **If on skin or hair:** take off immediately all contaminated clothing. Rinse skin with water / shower.
- If skin irritation occurs, get medical advice / attention and show the container or label.
- For more information please refer to Safety Data Sheet.

**Contains:** 2-BUTANONE OXIME. May produce an allergic reaction.

### WASTE MANAGEMENT

Do not empty surplus paint into drains, and do not dispose together with household refuse. Advice regarding disposal and collection should be sought from the local authorities.

**Note:** The information supplied in our literature or given by our employees, agents or distributors concerning the use of our products is based upon extensive experience and given in good faith in order to help you. We guarantee the consistent high quality of our products; however, as we have no control over site conditions of the executions of work, we cannot accept any liability for any loss or damage, which may arise as a result thereof.